



TDD#: T06-8810-28 Pg. 1 of 12

PHOTOGRAPHER/WITNESS #1 - roll 1

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/ 1056/ N

COMMENTS: Sign at entrance of site.

9820358





TDD#: T06-8810-28 Pg. 2 of 12

PHOTOGRAPHER/WITNESS # 2-4 - roll 1

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1102/E

COMMENTS: Drums at northeast area of site, behind
warehouse.



TDD#: T06-8810-28 Pg. 3 of 12

PHOTOGRAPHER/WITNESS #5 - roll1

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1103 / E

COMMENTS: Label on drum showing warnings
and original contents.



PHOTOGRAPHER/WITNESS #6 - roll1

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1104/ E

COMMENTS: Label on drum showing origin
and original contents of drum.



TDD#: T06-8810-28 Pg. 4 of 12

PHOTOGRAPHER/WITNESS # 7 - roll

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1105 / W

COMMENTS: Photo of interior of warehouse.



TDD#: T06-8810-28 Pg. 5 of 12

PHOTOGRAPHER/WITNESS # 8-10 - roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/ 1107/ NE NE

COMMENTS: Pan of NE corner of site showing drums,
vegetation, and spill on ground.



TDD#: T06-8810-28 Pg. 6 of 12

PHOTOGRAPHER/WITNESS #11 - roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1108 / NW

COMMENTS: Drum and liquid spill on north
side of the building.



PHOTOGRAPHER/WITNESS #12 - roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1108/ NW

COMMENTS: Photo shows spill, stressed
vegetation, drums and debris on north side
of the building.



TDD#: T06-8810-28 Pg. 7 of 12

PHOTOGRAPHER/WITNESS # 13- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1108 /N

COMMENTS: Stacked drums and stressed
vegetation on north side of property. Note
residence just beyond the fence.



PHOTOGRAPHER/WITNESS # 14- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1111/W

COMMENTS: Photo shows drums, stressed
vegetation and chemical stain.



TDD#: T06-8810-28 Pg. 8 of 12

PHOTOGRAPHER/WITNESS #15 - roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1112 / W

COMMENTS: Photo of drums, and one that
originally contained a herbicide.



PHOTOGRAPHER/WITNESS #16 - roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/ 1112/ E

COMMENTS: Interior of warehouse showing
drums, vat and debris.



TDD#: T06-8810-28 Pg. 9 of 12

PHOTOGRAPHER/WITNESS # 17- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1115 / E

COMMENTS: Drums and abandoned vehicles on
south end of site.



PHOTOGRAPHER/WITNESS # 18- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1117 / W

COMMENTS: Chemical stains in puddle near
SE corner of warehouse.



TDD#: T06-8810-28 Pg. 10 of 12

PHOTOGRAPHER/WITNESS # 19- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/ 1118/ E

COMMENTS: Inside of dumpster showing

polymer - like material.



TDD#: T06-8810-28 Pg. 11 of 12

PHOTOGRAPHER/WITNESS # 20-22- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1119/ E

COMMENTS: Pan of drums and debris in southeast area
of site. Note stains on ground.



TDD#: T06-8810-28 Pg. 12 of 12

PHOTOGRAPHER/WITNESS # 23- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/1122 / W

COMMENTS: Drums and stained ground on east
side of warehouse.



PHOTOGRAPHER/WITNESS # 24- roll 2

Richard Yeager

DATE/TIME/DIRECTION

8-19-88/ 1127/ NW

COMMENTS: Sign and entrance to site. Street
is Jensen Drive.

